



NIPPON KAIJI KYOKAI

TYPE APPROVAL CERTIFICATE

Certificate No. TA23654M

This is to certify that the undernoted products have been approved in accordance with the requirements 12.3.4, Chapt.12, Part D of "Rules for the Survey and Construction of Steel Ships" and Chapt.2, Part 6 "Guidance for the Approval and Type Approval of Materials and Equipment for Marine Use".

This certificate is issued to

Manufacturer:

TOFLE CO., INC., JAPAN

Place of Manufacturer:

1-6-16, Honmachi, Chuo-ku, Osaka-shi, Osaka

Product description:

FLEXIBLE TUBE

Type designation(s):

TF-10000

Approval No.:

14FV206B

Valid until:

12 February 2029

The details are described in the attached sheets.

Issued at Tokyo on 21 December 2023.

S. Oishi

General Manager

Machinery Department

· Particulars and conditions:

Nominal diameter (A):

65A, 80A, 100A, 125A, 150A

Design pressure (MPa):

65A:1.57MPa, 80A:1.13MPa, 100A:1.34MPa,

125A:1.38MPa, 150A:1.05MPa

Kind of fluid:

Fuel oil, Lubricating oil, Hydraulic oil, Thermal oil,

Steam, Fresh water, Sea water, Compressed air, Exhaust gas

· Material:

Tube:

SUS 304, SUS316L

Braid:

SUS304

Ring:

SUS304

· Type approval tests carried out:

Pressure test, Burst test, Fatigue test, Bend test, Leakage test

· Documents:

Drawing No.: MWH805727-B, MWH807614-A, MWH807615-A

· Installation requirements:

Installation of flexible hose assemblies are to comply with requirements 12.3.4, Chap.12, Part D of the Rules.

· Production test:

The hoses used for piping belonging to Group I & II defined by the requirements12.1.3, Chap.12, Part D of the Rules are to be subjected to hydraulic test in the presence of the Society's surveyor in accordance with the requirements 12.6.1, Chapt.12, Part D of the Rules.

· Approved manufacturers and address:

TOFLE OMEGA FLEX CO., INC.

886-1, Aza-Shiragami, Kawakami, Hagi-city, Yamaguchi-pref., JAPAN MITSUWA • WELDTECH CO., INC.

1-179, Chishiro-cho, Moriyama-city, Shiga-pref., Japan

Notice

Any significant changes in design or construction of the above items may render this certificate invalid.

- The End -